

MATERIAL SAFETY DATA SHEET

NAME OR NUMBER: DAP Weldwood Waterproof Resorcinol Glue (Powder Catalyst)

SECTION VII SPILL, LEAK AND DISPOSAL PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED:

Keep powder dry. Avoid creating dust by vacuuming up material or use sweeping compound if material is recovered by sweeping. Deposit spill residues in disposable containers.

WASTE DISPOSAL METHOD: Discarded spill residue may be incinerated. Do not incinerate sealed containers. Dispose according to Federal, State and local regulations.

SECTION VIII SPECIAL PROTECTION INFORMATION

RESPIRATORY PROTECTION: If ventilation is inadequate use an approved dust mask.

VENTILATION: Provide sufficient mechanical ventilation (local or general exhaust) to minimize dust levels.

PROTECTIVE GLOVES: Recommended for prolonged or repeated contact with skin

EYE PROTECTION: Goggles or safety glasses with side shields

OTHER PROTECTIVE EQUIPMENT: Provide eyewash and a dust mask

SECTION IX SPECIAL PRECAUTIONS

HANDLING AND STORING: Keep containers from excessive heat and freezing. Keep containers tightly closed when not in use. Keep out of reach of children.

OTHER PRECAUTIONS: Harmful or fatal if swallowed. Use only with adequate ventilation. Avoid prolonged or repeated exposure to dust and contact with skin. Wash contaminated clothing before reuse.

THIS DATA IS OFFERED IN GOOD FAITH AS TYPICAL VALUES AND NOT AS A PRODUCT SPECIFICATION. NO WARRANTY, EITHER EXPRESS OR IMPLIED, IS HEREBY MADE. THE RECOMMENDED INDUSTRIAL HYGIENE AND SAFE HANDLING PROCEDURES ARE BELIEVED TO BE GENERALLY APPLICABLE. HOWEVER, EACH USER SHOULD REVIEW THESE RECOMMENDATIONS IN THE SPECIFIC CONTEXT OF THE INTENDED USE AND DETERMINE WHETHER THEY ARE APPROPRIATE.

PREPARED BY: C.L. Johnson

REVIEWED BY: J.W. Rader

DATE: May 17, 1986

LAST REVISED: June 25, 1985